



Winners Run RICHMOND!

Ring and Pinion Sets


Corvette

MODEL	YEAR
Corvette	63-79

RATIO	PART NO.	TEETH
3.08	49-0097-1	40-13
3.36	49-0139-1	37-11
3.55	49-0021-1	39-11
3.70	49-0023-1	37-10
3.90	49-0031-1	39-10
4.11	49-0025-1*	37-9



*When replacing a 2.41 to 3.70 with a Richmond Ring and Pinion, the carrier must be replaced with a carrier from a stock 4.10 or numerically higher.



- 10-1/8" x 9-29/32"
- Irregular Housing 12 Holes
- 1.625" Diameter Pinion
- 30 Splines

INSTALLATION KIT/HALF KIT

PART NO.

83-1024-1	New
83-1024-B	Half-Kit

SPOOLS

PART NO. SPLINE CARRIER

Contact Factory

SPOOL BEARING KIT

PART NO.

Contact Factory

For Maximum Protection and Performance use Part # LUBE (pg 125)

RICHMOND GEAR
Synthetic Gear Oil



Always in stock at your local RICHMOND distributor



Phone: 864-843-9231 • Fax: 864-843-2964 • www.richmondgear.com